

# Oil Field Environmental Incident Summary

**Incident:** 20150227112921      **Date/Time of Notice:** 02/27/2015 11:29

**Responsible Party:** Key Energy Services

**Well Operator:** KEY ENERGY SERVICES, LLC

**Well Name:** North Dickinson SWD # 1

**Field Name:** RUSSIAN CREEK

**Well File #:** 6224

**Date Incident:** 2/27/2015      **Time Incident:** 01:30

**Facility ID Number:**

**County:** DUNN

**Twp:** 141

**Rng:** 96

**Sec:** 11

**Qtr:** NE NE

**Location Description:**

**Submitted By:** Jerry Sparling

**Received By:**

**Contact Person:** Jerry Sparling  
6389 104 th ave. NW  
Tioga, ND 58852

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	60	Barrels	60	Barrels	60	barrels
Other						

**Description of Other Released Contaminant:**

Produced brine water

**Inspected:**

**Written Report Received:** 12/8/2015

**Clean Up Concluded:** 3/6/2015

**Risk Evaluation:**

none

**Areal Extent:**

10,000 square feet

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

clean up is taking place now and will be completed by 3-2-15

**Wastes Disposal Location:** fluid has been placed into the salt water disposal and soil will be processed and hauled to Indian Hills Land facility

**Agencies Involved:**

**Updates**

---

**Date:** 2/27/2015    **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to pipeline leak, got off location. Followup is necessary.

---

**Date:** 3/2/2015    **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 3/2/15, at 12:00 p.m. Release ran from pipeline housing area to the east and started flowing south where it went off site in the SE corner of pad. Impacted area to field off site is approximately 75 x 50 feet. A call has been placed to One Call to mark location, and removal of soil will take place once area has been marked. More followup is required.

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received a hard copy of the cleanup report documenting the corrective actions taken in response to the production water release at 22nd and 25th Street SW, Dickinson, N.D. The report states that an environmental firm and subcontractor were dispatched for the cleanup. Free liquid was vacuumed and collected for disposal, and 11.55 tons of soil were removed for disposal at Chimney Butte Landfill. Report attached to the folder. Further followup needed.